

Project Profile



Beyond Traditional Taking Polishing to a whole new level

Osceola, WI - An airport hanger's current concrete floor needed to be repaired of spalled areas and surface delaminating due to salt damage. During the process, we also had the opportunity to "Trick" it out.

A cabin previously existed with just plain gray concrete. To add to the effect of a cabin by the lake, we decided

to add in a path that led from the door to the cabin, a deck area, and a lake effect.

Path: The path was grind and honed to a level 4 to expose larger aggregates. The path was also dyed to give a mottled look of gravel.

Deck: The deck area in front of the cabin is a stampable overlay, wood plank. The wood plank overlay was stained and sealed

Lake: The lake is a level 2 grind . Two different dyes were used and blended together to give the wavy, lake feel.



Project:
Custom Polish and
Stain

Location:
Airport Hanger
Osceola, WI

Problem:
Spall areas and
surface delaminating
due to salts.

Solution:
Mimic a look of
an airplane
landing by a
cabin on the
beach.

Results:
Grinded to a
level 4 to cre-
ate a path from
door to office
(cabin), stained
the pathway
for a mottled
look. Less grind
on main area
with a blend of
two dye colors.
Stampable over-
lay for deck area
with a Stain.



CONCRETE ARTS

ART WORK YOU CAN WALK ON

575 Schommer Drive
Hudson, WI 54016
WI: 715.386.8750
MN: 651.436.2525
Fax: 715.386.5600
www.ConcreteArts.com